



**RESUME WORK
IN THE MATTER OF THE NATIONAL ENERGY BOARD ACT,
FOLLOWING AN ORDER UNDER SECTION 51.1**

20 May 2015, 1200 HRS (Mountain

On Standard Time), the undersigned National Energy Board Inspection Officer hereby
Date/time

notifies [Redacted] that the hazardous or detrimental situation
Company Representative and company name

described in Order No. KAR-001-2014 has been remedied to the satisfaction of the Inspection Officer.
Inspection Officer order

Therefore, Suspended work may resume, and/or
 the measures specified in the order have been satisfied.

Inspection Officer		#1554	
	Name	IO Designation #	Telephone
	20 May 2015		
	Date		
Centre 10 – 517, 10th Avenue SW Calgary AB T2R 0A8			